

# Williams Visit Report

**School:** Wilson Elementary School

**Visit Date:** 9/13/2017

**Uniform Complaint Policies:** In Compliance

**SARC:** In Compliance

**Textbooks:**

**Document Review:**

1. ELA - sufficient
2. Math: - sufficient
3. Social Studies - sufficient
4. Science: - sufficient
5. ELD - sufficient

**Visitation:**

1. ELA - sufficient
2. Math: - sufficient
3. Social Studies - sufficient
4. Science: - sufficient
5. ELD - sufficient

**Overall Facilities Rating:** FAIR 83.63%

**Very clean for an old campus. The school is scheduled to close at the end of this school year. Very respectful and attentive staff!**

**Facility issues which affect the overall rating:**

1. Interior Surfaces
  - a. Bldg. 3 boys' restroom – duct tape on ceiling
  - b. Cafeteria – chipped paint
  - c. Room 2 – duct tape on ceiling
  - d. Room 3 – stained/damaged ceiling tile(s)
  - e. Room 19 – stained/damaged ceiling tile(s); overhead storage
  - f. Room 21 – stained/damaged ceiling tile(s)
  - g. Room 26 – stained carpet
2. Electrical
  - a. Bldg. 2 Rooms 9-12 (exterior) – missing light covers
  - b. Bldg. 3 boys' restroom – missing light covers
  - c. K2 – missing light's
  - d. Room 2 – cord management
3. Restrooms

## Williams Visit Report

- a. Bldg. 2 boys' restroom – inop urinals (standing water)
- b. Bldg. 3 boys' restroom – inop urinals
4. Sinks and Fountains
  - a. Bldg. 3 girls' restroom – faucet(s) inop/leaking
  - b. Bldg. 3 boys' restroom – inop paper towel dispenser
  - c. K2 – inop faucet
  - d. Room 26 – inop drinking fountain
5. Structural damage
  - a. YMCA portables (exterior) – missing boards (lower side skirting)
  - b. Library – missing board(s) lower side skirting
6. Playgrounds / school grounds
  - a. Building 1 (exterior) – main entrance school sign: large holes on side of sign
  - b. Kindergarten (exterior) – unabated weeds
  - c. Kindergarten play structure – chipped paint
  - d. Portables 19-26 – damaged boards/ramps
  - e. Basketball asphalt areas – missing basketball nets
  - f. Main play structure – chipped paint on structure; hole(s)/crack(s) in rubber matting