

Williams Visit Report

School: Rancho Medanos Jr. High School

Visit Date: 8/24/17

Uniform Complaint Policies: In Compliance

SARC: In Compliance

Textbooks:

Visitation:

1. ELA - sufficient
2. Math: - sufficient
3. Social Studies - sufficient
4. Science: - sufficient
5. ELD – sufficient
6. Foreign Language – sufficient

Document Review:

1. ELA - sufficient
2. Math: - sufficient
3. Social Studies - sufficient
4. Science: - sufficient
5. ELD - sufficient
6. Foreign Language – sufficient

Facility issues which affect the overall rating:

1. Interior Surfaces
 - a. Gymnasium – loose/damaged high curtain
 - b. D103 – damaged laminate
 - c. D104 – damaged laminate
 - d. E102 – overhead storage
 - e. E103 – missing paper towel dispenser
 - f. F204 – overhead storage
 - g. F201 – damaged laminate
 - h. F206 – damaged laminate
 - i. D203 – damaged laminate
2. Overall Cleanliness
 - a. Right stairwell – questionable service level/building hygiene (dust/dirt build-up and unabated stains)
 - b. Left stairwell – questionable service level/building hygiene (dust/dirt build-up and unabated stains)
 - c. D106 – overhead storage – garden equipment (shovels, rakes, etc.)

Williams Visit Report

3. Pest/Vermin Infestation
 - a. Grounds, front of school – unabated gophers and related damages
 - b. Grounds, West – unabated gophers and related damages
 - c. Grounds, North – unabated gophers and related damages
 - d. Grounds, South – unabated gophers and related damages
 - e. Grounds Main Quad Area - unabated gophers and related damages
4. Sinks and Fountains
 - a. E102 – inop faucet
 - b. F101 – inop faucet (sticks on)
 - c. F103 – inop faucet (sticks on)
 - d. F106 – inop faucet
 - e. F206 – inop faucet(s)
5. Structural damage
 - a. Grounds, front of school – concrete offset (trip/fall)
 - b. Grounds Main Quad Area - concrete offset (trip/fall)
 - c. E102 – damaged stucco above front door caused by teacher signage removal. (throughout campus)
6. Playgrounds / school grounds
 - a. Grounds, front of school – PSL: unabated weeds in lawns; 304” offset @ walkway to lawn. Transitions due to settled soils, causing raised /exposed utility boxes. Stressed, dying Trees.
 - b. Grounds, North – PSL: unabated weeds in lawns; 3-4” offset @ walkway to lawn. Tree wells not established. Irrigation in disrepair. Unabated erosion on sloped areas. Hypercom ground cover reflects stress and plant rust.
 - c. Grounds, South – PSL: unabated weeds in lawns; 3-4” offset @ walkway to lawn. Tree wells not established. Irrigation in disrepair. Unabated erosion on sloped areas. Hypercom ground cover reflects stress and plant rust.
 - d. Grounds track and field – PSL: irrigation in disrepair; grass areas reflect poor coverage. Stressed or dying lawn areas.
 - e. Grounds utility fields – PSL: irrigation in disrepair; grass areas reflect poor coverage. Stressed or dying lawn areas.
 - f. Grounds Main Quad Area - PSL: unabated weeds in ground covers. Irrigation in disrepair. Unabated erosion on sloped areas. Hypercom ground cover reflects stress and plant rust. Missing four trees at stairs leading to lower level. Tree wells.

*PSL = Poor Service Level

Overall Facilities Rating: GOOD 93.68%

Students were very engaged and classrooms were well managed!