

# Williams Visit Report

**School: Sun Terrace Elementary School**

**Visit Date: 8/25/17**

**Uniform Complaint Policies: In Compliance**

**SARC: In Compliance**

**Textbooks:**

**Document Review:**

1. ELA - sufficient
2. Math: - sufficient
3. Social Studies - sufficient
4. Science: - sufficient
5. ELD - sufficient

**Visitation:**

6. ELA - sufficient
7. Math: - sufficient
8. Social Studies - sufficient
9. Science: - sufficient
10. ELD – sufficient

**Overall Facilities Rating: GOOD 94.87%**

**Well organized for the visit. Administration helped us make efficient use of our time!**

**Facility issues which affect the overall rating:**

1. Interior Surfaces
  - a. Library – damaged ceiling tile(s)
2. Electrical
  - a. Bldg. A – cracked/damaged diffuser(s)
  - b. Bldg. B – cracked/damaged diffuser(s)
  - c. Bldg. B Girls' Restroom – inop light(s)
  - d. Library - inop light(s)
  - e. Bldg. A Boys' Restroom – unsecured diffuser(s)
  - f. D3 - inop light(s)
3. Restrooms
  - a. Bldg. A Girls' Restroom – inop toilet seat(s)
4. Sinks and Fountains
  - a. Bldg. A Boys' Restroom – inop faucet(s)
  - b. E4 – ino faucet (no hot water)
5. Playgrounds / school grounds
  - a. Large play structure – damaged foam padding; damaged rubber on the structure