

Williams Visit Report

School: El Cerrito High School

Visit Date: 8/30/17

Uniform Complaint Policies: In Compliance

SARC: In Compliance

Textbooks:

High schools in West Contra Costa Unified School District do not have textbook adoptions but rather a process in place so that materials for high school courses are reviewed centrally and recommended for specific courses. This procedure is out of compliance with Education Code Section 60400: The governing board of each school district maintaining one or more high schools shall adopt instructional materials for use in the high schools under its control.

Document Review:

1. ELA - sufficient
2. Math: - sufficient
3. Social Studies – sufficient
4. Science: - sufficient
5. ELD - sufficient
6. Foreign Language – sufficient

Visitation:

7. ELA - sufficient
8. Math: - sufficient
9. Social Studies - sufficient
10. Science: - sufficient
11. ELD – sufficient
12. Foreign Language – sufficient

Overall Facilities Rating: GOOD 95.73%

Very clean...infrastructure is well cared for. Students were engaged and respectful.

Facility issues which affect the overall rating:

1. Interior Surfaces
 - a. Bldg. A, Library – stained carpets
 - b. Cafeteria – damaged basedboards
 - c. B204 – missing pencil sharpener cover (hazard)
 - d. B207 – unsecured bookcase

Williams Visit Report

- e. C100 – unsecured bookcase
 - f. C106 – unsecured bookcase
 - g. C203 – missing pencil sharpener cover
2. Overall Cleanliness
- a. Gym lobby – unkempt exterior entry mats reflect poor service levels
 - b. C200 - clutter
3. Electrical
- a. Bldg. A, Library – inop light(s)
 - b. Bldg. B, Stairwell and hallways - inop light(s) (flickering)
 - c. Bldg. C, Girls’ 200 restroom – inop light(s)
 - d. Bldg. C, Girls’ 300 restroom – inop light(s)
 - e. Bldg. D, Boys’ restroom – inop light(s)
 - f. Small gym – damaged shut clock; damaged motion sensor
 - g. B206 – inop outlet (taped over)
 - h. C106 –cord management
 - i. D204 – ink on wall
4. Playgrounds / school grounds
- a. Bldg. A Administration – irrigation inop
 - b. Bldg. F, exterior - irrigation inop
 - c. Cafeteria bldg. - irrigation inop
 - d. General grounds - irrigation inop
5. Windows/doors
- a. Large gym – window film damaged at first level
 - b. Boys’ locker room – broken window